### **ENVIRONMENTAL CHEMISTS**

# Analysis For Total Metals By EPA Method 200.8

Client ID: M-05294 Client:
Date Received: 02/25/10 Project:
Date Extracted: 02/26/10 Lab ID:
Date Analyzed: 02/26/10 Data File:
Matrix: Water Instrumer
Units: ug/L (ppb) Operator:

 Project:
 Metro Self Monitor, F&BI 002241

 Lab ID:
 002241-01 x10

 Data File:
 002241-01 x10.030

 Instrument:
 ICPMS1

 Operator:
 AP

Alaskan Copper Works

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 99 60 125

Concentration ug/L (ppb)

Chromium 369
Nickel 369
Copper 448
Zinc 34.2

### **ENVIRONMENTAL CHEMISTS**

## Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank Alaskan Copper Works Client: Date Received: Not Applicable Project: Metro Self Monitor, F&BI 002241 Lab ID: Date Extracted: 02/25/10 I0-92 mb I0-92 mb.017 Data File: Date Analyzed: 02/26/10 ICPMS1 Matrix: Water Instrument: Units: Operator: AP ug/L (ppb)

		Lower	Upper
Internal Standard:	% Recovery:	Limit:	Limit:
Germanium	96	60	125
Indium	98	60	125
Holmium	100	60	125

<1

Concentration Analyte: ug/L (ppb) <1 Chromium Nickel <1 Copper <1 Zinc

#### **ENVIRONMENTAL CHEMISTS**

Date of Report: 03/04/10 Date Received: 02/25/10

Project: Metro Self Monitor, PO M-05294, F&BI 002241

# QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 002217-02 (Duplicate)

Analyte	Reporting Units	Sample Result	Duplicate Result	Percent Difference	Acceptance Criteria
Chromium	ug/L (ppb)	1.24	2.40	64 a	0-20
Nickel	ug/L (ppb)	8.17	8.37	2	0-20
Copper	ug/L (ppb)	3.07	2.93	5	0-20
Zinc	ug/L (ppb)	5.27	5.37	2	0-20

Laboratory Code: 002217-02 (Matrix Spike)

				Percent	
Analyte	Reporting Units	Spike Level	Sample Result	Recovery MS	Acceptance Criteria
Chromium	ug/L (ppb)	20	1.24	104	67-132
Nickel	ug/L (ppb)	20	8.17	100 b	73-119
Copper	ug/L (ppb)	20	3.07	96	50-144
Zinc	ug/L (ppb)	50	5.27	98	46-148

Laboratory Code: Laboratory Control Sample

Analyte		pike evel	Percent Recovery LCS	Acceptance Criteria
Chromium	ug/L (ppb)	20	108	66-135
Nickel	ug/L (ppb)	20	111	67-134
Copper	ug/L (ppb)	20	105	66-134
Zinc	ug/L (ppb)	50	106	57-135

#### **ENVIRONMENTAL CHEMISTS**

## **Data Qualifiers & Definitions**

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb Analyte present in the blank and the sample.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht Analysis performed outside the method or client-specified holding time requirement.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- il The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve Estimated concentration calculated for an analyte response above the valid instrument calibration range. A dilution is required to obtain an accurate quantification of the analyte.
- vo The value reported fell outside the control limits established for this analyte.
- x The sample chromatographic pattern does not resemble the fuel standard used for quantitation.

#### **ENVIRONMENTAL CHEMISTS**

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

March 4, 2010



Accounts Payable Alaskan Copper Works 628 South Hanford Seattle, WA 98134

RE: Project Metro Self Monitor, PO M-05294, F&BI 002241 - Results of testing requested by Gerry Thompson for material submitted on February 25, 2010.

FEDERAL TAX ID #(b) (6)

002241				MPLE CHA	in of c	US'	loı	Y			ME		2].	25/1	0		ALY
Sand Banart To Took	The	050-1		SAMPLERS	isionoturei			_	_						lage :	NA DOLIN	_ of
Send Report To Gerrer Thompson  Company ALASKAN Coppen Works			PROJECT NAME/NO. PO #					$\dashv$	TURNAROUND TIME    Standard (2 Weeks)								
Address 628 S. Harond ST		1					m	M-05294			Rush God Rush charges authorized by:						
	1												4	<u></u>		IPLE DIS	
City, State, ZIP_SEATT	re W	4 98	3134_	REMARKS											spose	after 30	
Phone # 206-571-603	33_Fax #_2	o6-382	-4309													samples with inst	ructions
		T				_				ANA	LYSE	S RE	OUE	STED			
					74 40	_	ne	21B				3					
Sample ID	Lab ID	Date	Time	Sample Type	# of containers	TPH-Diesel	TPH-Gasoline	STEX by 803	VOCs by 82	SVOCs by 8270	Ĭ,	the Carre					Notes
M-05294	01	2/25/10	12:30	H2O	1										上		
					100												a managaran
											_	1	_				- 4m m
	_								2	$\dashv$	+	+	+		$\vdash$	-	
						H			-	+	+	+	+	+	╁	├	·
<del></del>				<u> </u>					-	+	-	+	+	+	+	+-	
	- <b>!</b>									$\dagger$	1	$\dagger$	$\dagger$	-	+		
										7		$\dagger$	1				
Friedman & Bruya, Inc.		SIGNATU	RE		PRINT		_			-		СОМ	_	Y		DATE	TIME
3012 16th Avenue West	Relinquisties	7		1 4 0/1	Enav 1	_	w			-		CE			_ 3	25/10	1:52pm
Seattle, WA 98119- Ph. (206) 285-8282	Received by:  M Relinquished b	/am	)	101	16n	P	na	<u>~</u>		+	F.	e B	I		- -	425/10	1:52 a
Fax (206) 283-5044	Received by:						Walley Control										
FORMS\COC\COC.DOC		****															<u> </u>

#### **ENVIRONMENTAL CHEMISTS**

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

March 4, 2010

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on February 25, 2010 from the Metro Self Monitor, PO M-05294, F&BI 002241 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Kortland Orr Project Manager

Enclosures ACU0303R.DOC